

Full Surface Geared Hinges

SL57 95" HD

All dimensions are measured in inches and [millimeters] from the top of the door to the centerline of the holes and bearings.

Dimensions shown inside boxes _____ are frame facing mounting screw holes.

Choose location for CTW prep from bearing slots dimensioned. CTW4/5 = 1 location; CTW8/10 = 2 locations; CTW12 = 3 locations.

SL57 Profile



